



Technical Bulletin



Manufacturer: Chrysler (TSB 09-003-08)

Service Plus Group: 07-17-0607

Subject: 3.0L Diesel Alternator Inoperative

Model: 2007-2008 (WK) Grand Cherokee

NOTE This bulletin applies to all 2007-2008 WK vehicles equipped with 3.0L diesel engine (sales code EXL).

Condition

The customer or technician may notice oil marks on the alternator. This condition can only happen while pouring the oil into the engine and care is not taken to ensure none is spilled.

Diagnosis

If the alternator is inoperative, perform this repair procedure.

Repair Procedure

1. Replace the alternator.
2. Install the splash shield (p/n 04801798aa) on top of the alternator. This splash shield snaps into the grooves on top of the alternator.

Qty	Part #	Description
1	04801798AA	Splash Shield