



SERVICE PLUS TECHNICAL BULLETIN

Manufacturer: Ford

Service Plus Group: 08-01-0205

Subject: No Crank - Battery Discharged - 3.0L 4V

Model: 2004-2005 Ford Taurus
2004-2005 Mercury Sable

Issue

Some 2004-2005 Taurus/Sable vehicles built before 8/27/2004 equipped with a 3.0L 4-valve engine may exhibit a no crank, battery discharged condition.

Action

Reprogram the powertrain control module (PCM) to the latest calibration using WDS release B34.7 or higher. Calibration files may also be obtained at www.motorcraft.com. If a charging concern is still present after PCM reprogramming, perform normal diagnostics.

NOTE Refer to appropriate Ford Service Information for all repairs.