



# Technical Bulletin



**Manufacturer:** Ford (TSB 07-6-2)

**Service Plus Group:** 09 -12-0507

**Subject:** Malfunction Indicator Light (MIL) -Multiple Diagnostic Trouble Codes (DTCS) and/or Possible Low Battery Rate of Charge

**Model:** 2005 Crown Victoria,  
2005 Grand Marquis  
2005 Town Car

### **Issue**

Some 2005 Crown Victoria, Grand Marquis and Lincoln Town Car vehicles may exhibit one or more of the following DTC's: P0316, P030X and P0606. This calibration also includes a strategy to optimize the battery charging capability.

### **Action**

The vehicle needs to go to the Ford dealership to reprogram the powertrain control module (PCM) to the latest calibrations.