



Total Car Care Technical Service Bulletins



Manufacturer: General Motors (Bulletin # 10-01-37-001A)

TCC Group: 02-07-0410

Subject: HVAC Blower Motor Inoperative, Blower Motor Operates on High Speed Only

Model: 2004-2010 Chevrolet Aveo
2005-2009 Pontiac Wave (Canada Only)
2009-2010 Pontiac G3, G3 Wave (Canada Only)
2006-2010 Holden Baris

Issue

Some customers may comment that the blower will only operate on high speed or has become inoperative. This condition may be caused by an open resistor. The blower motor operates correctly after replacing the resistor, but the resistor may fail again due to a faulty blower motor.

Action

Replace the blower motor and resistor.

Parts Information

Part Number	Description	Usage
96539656	Motor Blower	LHD, A/C
96539676	Motor Blower	LHD, Heater Only
96539567	Motor Blower	RHD, A/C
96539721	Motor Blower	RHD, Heater Only
9650490	Resistor Blower	For Full Automatic Temperature Controller (FATC)
96435889	Resistor Blower	For Non Full Automatic Temperature Controller (FATC)