



# SERVICE PLUS TECHNICAL BULLETIN

**Manufacturer:** Mitsubishi

**Service Plus Group:** 07-03-1104

**Subject:** Engine Performance

**Model:** 2003-2005 Montero  
2004 Outlander  
2004 Lancer  
2004 Lancer Sportback w/2.4L MIVEC Engine  
2004 Galant

Whenever any of the following repairs are made an Electronic Throttle Valve (ETV) initialization procedure should be performed.

- Throttle Body Cleaning
- Throttle Body Replacement
- PCM Replacement

To perform the procedure:

Turn the ignition on (without starting the engine) then off and keep it off for atleast 10 seconds before starting the engine.

There is one other thing you must be aware of when replacing the PCM on many late model Mitsubishi vehicles. If the vehicle is equipped with the Mitsubishi Anti-theft engine immobilizer system, the ignition key must be registered to the PCM or the vehicle will not start. The registration procedure can only be performed using dealer specific equipment.