

Manufacturer: Mitsubishi

Complete Car Care Group: 01-04-1105

Subject: Oil Filter Installation

Model: Eclipse, Galant, Endeavor models equipped with 3.8L/V6

Due to the small clearance between the oil filter and serpentine belt, incorrect filter installation/removal could result in damage to the belt. If the oil filter guard is bent toward the belt, its sharp edges may contact the belt.

After installing the oil filter, start the engine and listen for a serpentine belt noise. Adjust the oil filter guard as necessary to eliminate contact with the belt.

