



Technical Advisory Bulletin

Mistubishi FWD Flywheel Spacers

Manufacturer: Mitsubishi

Subject: Flywheel Spacers

Model: 2006 Eclipse 2.4L

On 4-cylinder models, the flywheel has a spacer on each side. The spacers are different and must be installed in the proper position. Spacer p/n MD365791 has no lip on the inside diameter, so that it can be installed flush against the crankshaft. Spacer p/n MD365781 has a lip on the inside diameter, and is installed on the other side of the flywheel.

