



# Technical Bulletin



**Manufacturer:** Ford (TSB 07-17-1) **FLEET VEHICLES**

**Complete Car Care Group:** 04-07-0108

**Subject:** Early Wear of the Inner Brake Pad on the Rear Disc Brakes

**Model:** 2004-2007 E250, E350

## **ISSUE**

Some 2004-2007 E-Series 250/350 vehicles may exhibit early wear of the inner brake pad on the rear disc brakes when operated in mud, slush, dirt, or other severe conditions. Full rear brake dust shield assemblies have been released for service.

## **ACTION**

Install two (2) rear brake dust shield assemblies

### **NOTE**

The Rear Brake Dust Shield Assemblies are Identical for the Left and Right Side. The Service Parts are Different for Vehicles Built Prior to 11/29/2004.

### **NOTE**

For E-350 SRW Cutaway Vehicles Only, Parts are Unique. The Parts are Not Interchangeable.

- Shallow shields are available for dual rear wheel (DRW) with single rear (SRW) axle and outboard rotors that are protected by the single rear wheel.
- Deep shields are available for SRW service - only for SRW axles with inboard rotors that are not protected by the single rear wheel.

Part Number	Part Name
1C2Z-2390-AB	Brake Shield (Shallow) -E250/350 DRW built prior to 11/29/2004
5C2Z-2390-AA	Brake Shield (Shallow) - E250/350 DRW built after 11/29/2004
1C2Z-2390-BA	Brake Shield (Deep) - E250/350 cut SRW Built prior to 11/29/2004
5C2Z-2390-BA	Brake Shield (Deep) - E250/350 cut SRW Built after 11/29/2004