



ZF6HP26

Bind up on the 3-4 shift

File: ZF6HP26
Date: November 2015

Bind up on the 3-4 shift

If you are rebuilding a ZF6 series transmission be very careful while replacing the check balls. The ZF valve body comes with check balls that measure (.236"). Some aftermarket gasket sets come with generic quarter inch (.250") checkballs. If you install these (.250") check balls you will have shifting issues.

Always measure the check balls before replacing them. It is a good idea to perform this task when replacing check balls on all valvebodies especially if the unit is new and unfamiliar to you.

