



Technical Advisory Bulletin

Mitsubishi A/T Learned Value Reset Procedure

Manufacturer: Mitsubishi

Subject: A/T Learned Value Reset Procedure

Model: 2004 Galant and Endeavor
2005 All Models

Mitsubishi recommends resetting the computer A/T learned values when any of the following repairs are performed:

- Automatic transmission replacement
- Engine replacement
- Automatic transmission valve body or solenoid replacement

On any of the affected vehicles the A/T learned values cannot be reset by disconnecting the battery. A scan tool must be used. As of now the only tool capable of doing this is the dedicated Mitsubishi scanner.