



**Technical
Advisory Bulletin**

Mitsubishi

**Valve Body Gasket
Deleted for FW4A & FW5A
Transmissions**

Manufacturer: Mitsubishi (TSB# 07-23-008)

Subject: Valve Body Gasket Deleted for FW4A & FW5A
Transmissions

Affected Models:

Mirage	1997 & Later
Lancer	2002-2007
Diamante	1997-2004
Eclipse	2000-2008
Eclipse Spyder	2001-2008
Galant	1999-2008
Outlander	2003-2006
Endeavor	2004-2008

This TAB advises that the valve body gasket for FW4A and FW5A (40/50 series) automatic transmissions have been deleted from production. It also advises that during servicing, it is not necessary to refit the gasket even if the transmission was originally produced with one. Assembling the transmission without re-installing the gasket produces no negative effect on its performance and operation.