



# Technical Advisory Bulletin

# GM

## Aisin Automatic Transmission "Slip Control System" (SCS) New Fluid Reminder

**Manufacturer:** General Motors

**Subject:** Aisin Automatic Transmission "Slip Control System" (SCS)  
New Fluid Reminder

**Model:** 2007 Chevrolet W-Series Medium Duty Tilt Cab Models  
2007 GMC W-Series Medium Duty Tilt Cab Models  
2007 Isuzu NPR Commercial Models with 12,000 lbs GVW  
and 5.2L 4HK1-TC Diesel Engine (DPF Filter System)  
2008 Chevrolet W-Series Medium Duty Tilt Cab Models  
2008 GMC W-Series Medium Duty Tilt Cab Models  
2008 Isuzu NPR/NPR-HD/NQR/NRR Commercial Mode  
with 5.2L 4HK1-TC Diesel Engine

These Aisin transmissions require a specialized "Slip Control System" (SCS) fluid. This fluid was developed to work in conjunction with new clutch pack material to provide a positive shift and to reduce wear. This new Isuzu SCS Automatic Transmission Fluid will need to be used whenever an Aisin transmission with the SCS feature is serviced.

After servicing the transmission, the fluid level **MUST** be set/adjusted correctly. Refer to the Factory Service Manual for the proper automatic transmission fluid adjustment procedure.

**NOTE**

If the transmission fluid level is overfilled or underfilled, it may damage the transmission.

### For Chevrolet and GMC Models

Part Number	Description	Qty
97779615	Fluid, Automatic Transmission Aisin SCS ATF	1 qt
97779553	Fluid, Automatic Transmission Aisin SCS ATF	5 gal.

### For Isuzu Models

Part Number	Description	Qty
2-90531-200-0	Fluid, Automatic Transmission Aisin SCS ATF	1 qt
2-90531-201-0	Fluid, Automatic Transmission Aisin SCS ATF	5 gal.